

* Map Ref. #	Address	Date	Duration of Overflow (hrs)	Estimated Volume (gallons)	Basin	Cause of the Overflow	2005 Sanitary Sewer Overflow Report		Long Term Planning and Remediation
							Measure taken to stop the Overflow	Short Term Control List	
1	WWTP	7-Jan-2005	42 hrs		Blair Lane	Overflow was due to excessive flows	Flow was diverted to the EQ basin when possible in an attempt to the minimize volume of the overflow		X
1	WWTP	13-Jan-2005	50 hrs		Blair Lane	Overflow was due to excessive flows	Flow was diverted to the EQ basin when possible in an attempt to the minimize volume of the overflow		X
1	WWTP	20-Feb-2005	84 hrs		Blair Lane	Overflow was due to excessive flows	Flow was diverted to the EQ basin when possible in an attempt to the minimize volume of the overflow		X
1	WWTP	2-Mar-2005	4 hrs 30 min		Blair Lane	Overflow was due to excessive flows	Flow was diverted to the EQ basin when possible in an attempt to the minimize volume of the overflow		X
1	WWTP	1-Apr-2005	90 hrs		Blair Lane	Overflow was due to excessive flows	Flow was diverted to the EQ basin when possible in an attempt to the minimize volume of the overflow		X
1	WWTP	7-Apr-2005	77 hrs		Blair Lane	Overflow was due to excessive flows	Flow was diverted to the EQ basin when possible in an attempt to the minimize volume of the overflow		X
1	WWTP	16-May-2005	12 hrs 45 min		Blair Lane	Overflow was due to excessive flows	Flow was diverted to the EQ basin when possible in an attempt to the minimize volume of the overflow		X
1	WWTP	26-May-2005	1 hr		Blair Lane	Overflow was due to excessive flows	Flow was diverted to the EQ basin when possible in an attempt to the minimize volume of the overflow		X
1	WWTP	31-May-2005	1 hr		Blair Lane	Overflow was due to excessive flows	Flow was diverted to the EQ basin when possible in an attempt to the minimize volume of the overflow		X
1	WWTP	30-Aug-2005	12 hrs		Blair Lane	Overflow was due to excessive flows	Flow was diverted to the EQ basin when possible in an attempt to the minimize volume of the overflow		X
2	617 N Cumberland	13-Jan-2005	15 min	5 gpm	Sinking Creek	Grease in Line	Servicemen cleaned the main line.		
3	West Spring St.	15-Feb-2005	10 min	5 gpm		Grease in Line	Servicemen cleaned the main line.		
4	627 N Cumberland	18-Feb-2005	15 min	5 gpm	Sinking Creek	Grease in Line	Servicemen cleaned the main line.		
5	306 Neal St.	21-Feb-2005	9 hrs	275 gpm	Bartons Creek	Excessive rainwater	None		
5	306 Neal St.	30-Aug-2005	6 hrs 20 min	100 gpm	Bartons Creek	Excessive rainwater	None		
6	805 Tennessee Blvd	28-Mar-2005	4 hrs	100 gpm	Sinking Creek	Blockage	Servicemen cleaned the main line.	X	
7	805 Kent Dr.	3-Apr-2005	10 min	25 gpm	Tarver Branch	Blockage	Servicemen cleaned the main line.	X	
8	921 East Baddour Pkwy	31-May-2005	15 min	5 gpm	Sinking Creek	Blockage	Servicemen repaired the manhole.	X	
9	Maddow Simpson Pkwy	8-Jun-2005	5 min	5 gpm		Blockage	Servicemen cleaned the main line.	X	
10	Reed St	13-Jun-2005	15 min	5 gpm	Sinking Creek	Blockage	Servicemen cleaned the main line.	X	
11	Plantation South Blvd Pump Station	8-Jul-2005	1 hr 40 min	5 gpm	Blair Lane	Electrical Outage - No Power	Servicemen repaired the pump station.		
11	Plantation South Blvd Pump Station	25-Aug-2005	25 min	5 gpm	Blair Lane	Electrical Outage - No Power	Servicemen repaired the pump station.		
12	Posey Hill Pump Station	26-Jul-2005	5 min	5 gpm		Air Compressor not turned on	Servicemen repaired the pump station.		
13	Byars Dowdy School Dawson Ln & Hickory Ridge	29-Aug-2005		50 gpm	Bartons Creek	Excessive rainwater	None		
14	Vincent Cason	30-Aug-2005	5 hrs 20min	25 gpm	Bartons Creek	Excessive rainwater	None		
15	1001 Keaton St.	30-Aug-2005	5 hrs 20 min	50 gpm	Bartons Creek	Excessive rainwater	None		
16	Neal St & West St.	30-Aug-2005	7 hrs 20 min	25 gpm	Bartons Creek	Excessive rainwater	None		
17	302 Neal St.	30-Aug-2005	7 hrs 20 min	25 gpm	Bartons Creek	Excessive rainwater	None		
18	216 East Main St.	30-Aug-2005	5 hrs 10 min	25 gpm	Sinking Creek	Excessive rainwater	None		
19	424 Beard St.	30-Aug-2005	5 hrs	50 gpm	Sinking Creek	Excessive rainwater	None		
19	424 Beard St.	30-Aug-2005	12 hrs 45 min	150 gpm	Sinking Creek	Excessive rainwater	None		
20	Carver Lane Pump Station	30-Aug-2005	50 min	5 gpm	Blair Lane	Excessive rainwater	None		
21	Barnes Drive Pump Station	30-Aug-2005	14 hrs 20 min	50 gpm	Blair Lane	Excessive rainwater	None		

2005 Sanitary Sewer Overflow Report								
21	Barnes Drive Pump Station	12-Sep-05	5 min	5 gpm	Blair Lane	Pump went out	Servicemen repaired the pump station.	
21	2201 Barnes Dr.	20-Nov-2005	10 min	5 gpm	Blair Lane	Pump running all day	Servicemen repaired the pump station.	
22	Kensington Pump Station	12-Sep-2005	5 min	5 gpm	Blair Lane	Pump went out	Servicemen repaired the pump station.	
23	518 West Main St. Quick Stop	12-Sep-2005	5 min	5 gpm	Tarver Branch	Blockage	Servicemen repaired the main line.	X
24	Five Oaks Pump Station	14-Sep-2005	30 min	25 gpm	Blair Lane	Pump went out	Servicemen repaired the pump station.	
25	319 East Main St.	11-Oct-2005	5 min	5 gpm	Sinking Creek	Blockage	Servicemen cleaned the main line.	X
26	Summer Crest Pump Station	11-Oct-2005	5 min	100 gpm	Blair Lane	Pump went out	Servicemen repaired the pump station.	
27	802 Tennessee Blvd Tommy's Auto Repair	19-Oct-2005	1 hr 15 min	50 gpm	Sinking Creek	Blockage	Servicemen cleaned the main line.	X
28	Peyton Rd. Peyton Park Apts.	2-Nov-2005	40 min	25 gpm	Sinking Creek	Blockage	Servicemen cleaned the main line.	X
29	Walkers Branch Pump Station	31-Aug-2005	7 hr 30 min		Walkers Branch	Excessive rainwater	None	