

Don Fox Community Park

Parking

About 120 total parking spaces with four designated accessible spaces, two of which are van accessible.

ADAAG: Parking lots with 101 to 150 total parking spaces require five accessible parking spaces minimum (208.2).

Path of Travel

There are two ramps to the restrooms. The ramp from parking has about a 1:12 slope for more than a 6 inch rise and no handrails. The ramp from the middle of the park has about a 1:9 slope, a 1:18 cross slope, and no handrails.

ADAAG: Ramp runs shall have a running slope not steeper than 1:12 (405.2). Cross slope of ramp runs shall not be steeper than 1:48 (405.3). Ramp runs with a rise greater than 6 inches shall have handrails complying with 505 (405.8).

Picnic Tables

All four picnic shelters have one picnic table that is accessible for people who use wheelchairs. There are picnic tables by themselves on grass in the park and none are accessible models.

ADAAG: Accessible dining surfaces shall be distributed throughout the space containing dining surfaces (226.2).

Wading Pool

The wading pool is on an accessible route but there is no accessible means of entry to the pool, though adding compliant handrails might provide transfer walls.

ADAAG: At least one accessible means of entry complying with 15.8.5 (sloped entries), 15.8.6 (transfer walls), or 15.8.7 (transfer systems), shall be provided for each wading pool (15.8.2, proposed rec. guidelines).

Play Areas

One of the two play areas with elevated play stations is designed for accessibility with transfer steps for access. The equipment and swings are in loose wood chips. There is a wood walk that slopes down to the wood chips at a 1:9 to 1:10 slope. There is a 2 inch unbeveled change in level at the transition of the ramp and the wood chips.

ADAAG: Floor and ground surfaces shall be stable, firm and slip-resistant (302.1). Ramp runs shall have a running slope not steeper than 1:12 (405.2). Changes in level greater than ½ inch high shall be ramped and comply with 405 or 406 (303.4).

Restrooms

Signage does not include Braille or raised characters.

ADAAG: Signs identifying permanent rooms and spaces shall include raised characters that comply with 703.1 that are duplicated in Braille that complies with 703.2 (216.2).

The stall door opens into the men's toilet stall and swings both ways in the women's. The back grab bar is 24 inches long and the 42 inch side grab bar is mounted 4 inches from the rear wall in both rooms.

ADAAG: Toilet stall doors shall be self-closing and shall not swing into the minimum required compartment area (604.8.1.2). The rear grab bar shall be 36 inches long minimum (604.5.2). The side wall grab bar shall be 42 inches long minimum located 12 inches maximum from the rear wall and extending 54 inches minimum (604.5.1).

The lavatory supports reduce the knee clearance to a width of 14 inches in the women's room. The mirrors are 50 inches high in both rooms.

ADAAG: Knee clearance shall be 30 inches minimum in width (306.3.5). Mirrors shall be installed with the bottom edge of the reflecting surface 40 inches maximum above the floor (603.3).